Wesleyan University

Capital & Major Maintenance Projects
Before & After Photos
FY 2019/2020

Capital Projects

291 MAIN STREET - RENOVATION FURNITURE-BEFORE















√ Wesleyan University

291 MAIN STREET - RENOVATION FURNITURE









CENTER FOR FILM STUDIES – CONSTRUCTION NEW ADDITION AND RENOVATION







Before In Progress

√ Wesleyan University FY 20 Before and After

CENTER FOR FILM STUDIES – CONSTRUCTION NEW ADDITION AND RENOVATION

In Progress











│ Wesleyan University

SHANKLIN ROOM 316 OFFICE RENOVATION

Before

















√7 Wesleyan University

FY 20 Before and After
















After

Before









、 Wesleyan University

COMP 12: LED LIGHTING UPGRADES

Foss Hill Drive LED lighting Upgrade
Central Power Plant LED Lighting
Van Vleck Observatory LED Lighting Upgrade
291 Main Street LED Lighting Upgrade
Memorial Chapel/ Zelnick Pavillion
Allbrittion LED Lighting Upgrade

EXLEY DATA CENTER COMPREHENSIVE ENERGY PHASE 12: EXLEY DATA CENTER HVAC UPGRADES

Before



After











√ Nesleyan University

FIRE SAFETY UPGRADES – NEW FIRE ALARM & FIRE SPRINKLER SYSTEMS 31 NEW UNDERGRAD BEDS CREATED







38/40 Brainerd Avenue



47 Brainerd Avenue







√ Wesleyan University

39 Brainerd Avenue

FY 20 Before and After








Wesleyan University

CFA A ADZENYAH REHEARSAL HALL - ADA UPGRADES – HOW WE GOT THERE


















CFA A ADZENYAH REHEARSAL HALL - ADA UPGRADES















√ 7 Wesleyan University

CFA A ADZENYAH REHEARSAL HALL - ADA UPGRADES - AFTER






















ر T Wesleyan University








√ T Wesleyan University

EXLEY - IDEAS SPACE - AFTER

FY 20 Before and After













Wesleyan University

FREEMAN ATHLETIC CENTER INFORMAL LEARNING SPACE- BEFORE















FY 20 Before and After

FREEMAN ATHLETIC CENTER INFORMAL LEARNING SPACE- AFTER













Wesleyan University


























240 WASHINGTON STREET - INFORMAL LEARNING SPACE UPGRADES





Before



Wesleyan University















200 CHURCH STREET- INFORMAL LEARNING SPACE UPGRADES

Before





After





√7 Wesleyan University

FY 20 Before and After

202 WASHINGTON STREET- INFORMAL LEARNING SPACE UPGRADES

















SANIGLAZE TILE RESTORATION

Public Affair Center










Foss 1-4 Bathrooms









ヿ ゚ Wesleyan University

SANIGLAZE TILE RESTORATION

Russell House





Fisk Hall







て Wesleyan University

Major Maintenance FY20 Projects

274 COURT STREET - APARTMENT #103 - KITCHEN RENOVATION

Before After





1 LONG LANE -KITCHEN AND BATHROOM RENOVATION

Before














ر T Wesleyan University FY 20 Before and After

7 LONG LANE -KITCHEN AND BATHROOM RENOVATION



After

Before











After







ر T Wesleyan University





Wesleyan University









After









√ [¬] Wesleyan University

FOSS HILL UNIT 9 -FLOOR REPLACEMENT

Before



て Wesleyan University



RUSSELL HOUSE -350 HIGH ST - EXTERIOR CURVED STAIRS

Before




て Wesleyan University







Before ______After





Construction





√ Wesleyan University

Before



After



FY 20 Before and After Before

OLIN MEMORIAL LIBRARY – COMMON AREA CARPET REPLACEMENT 1ST & 2ND FLOORS










Wesleyan University

OLIN MEMORIAL LIBRARY – COMMON AREA CARPET REPLACEMENT 1ST & 2ND FLOORS



Before



After





、ヿ ` Wesleyan University

OLIN MEMORIAL LIBRARY – STAFF LOUNGE FLOOR REPLACEMENT

Before





Wesleyan University





Before: Men










Before: Women







√ Wesleyan University



After



Wesleyan University
















110 CHURCH ST - EXTERIOR WATERPROOFING

Before







After







ر T Wesleyan University

2 FOUNTAIN AVE -FLOORING/LIGHTING

Before













Wesleyan University







After










Wesleyan University

FY 20 Before and After

Before





2 WARREN ST - FLOORING/ LIGHTING











After









√ T Wesleyan University

FY 20 Before and After

CFA CROWELL CONCERT HALL -MECHANICAL SYSTEM UPGRADES AND SKYLIGHT REPLACEMENT

Before







After











EXLEY SCIENCE LIBRARY- 1ST AND 2ND FLOOR MEN'S AND WOMEN'S RESTROOMS REFRESH

Before

Men's Room















FY 20 Before and After

EXLEY SCIENCE LIBRARY- 1ST AND 2ND FLOOR MEN'S AND WOMEN'S RESTROOMS REFRESH

Before

Women's Room







く^フ Wesleyan University










CFA P THEATER - ROOF MOUNTED SMOKE HATCHES

Before













FY 20 Before and After

CFA P THEATER – INSTALL GALLERY SAFETY RAILS







CFA P THEATER – INSTALL NEW HANDRAILS

After

Before








√ Wesleyan University

WOODFRAME STRUCTURAL FLOOR REPAIRS

Before After





After

Before

















√ [™] Wesleyan University

33 BRAINARD AVE- ROOF REPLACEMENT

Before





Wesleyan University








FISK HALL -262 HIGH ST- 3RD FLOOR CARPET REPLACEMENT

Before



After











Wesleyan University



















After






ע ٦ Wesleyan University











After





















√ Wesleyan University

227 PINE ST - WOODFRAME HOUSING - EXTERIOR PAINTING

After









て Wesleyan University

ALSOP HOUSE- WOOD SOFFIT REPAIRS

FY 20 Before and After

Before





240 COURT ST #6 KITCHEN REMODEL

Before









28 LAWN AVE - WOODFRAME HOUSING - EXTERIOR PAINTING/VINYL

Before





√ Wesleyan University









DAVISON HEALTH CENTER CLINIC ROOF REPLACEMENT

Before





79 LAWN AVE - INTERIOR RENOVATION/FIRE SAFETY UPGRADES
























FY 20 Before and After



FREEMAN ATHLETIC CENTER -FIRE ALARM UPGRADE



FY 20 Before and After

146 HIGH STREET - WOODFRAME HOUSING - EXTERIOR PAINTING

Before











7 VINE ST - EXTERIOR VINYL SIDING/ FLOORING















∖ [™] Wesleyan University


59 PEARL STREET - ROOF REPLACEMENT

Before





After



√ Wesleyan University

FOSS HILL UNIT 3 – ROOF REPLACEMENT

Before



√ Wesleyan University





Before





FY 20 Before and After

FOSS HILL 6-7 CONNECTOR – ROOF REPLACEMENT

Before



After



Wesleyan University

FOSS HILL UNIT 5.5 - ROOF REPLACEMENT

Before













√ 7 Wesleyan University

OLIN/PAC CONNECTOR-ROOF REPLACEMENT

Before



Wesleyan University

After







CFA ART STUDIO SOUTH – ROOF REPLACEMENT


FY 20 Before and After

Before



After





√ Wesleyan University



After





√ Wesleyan University

DAVISON HEALTH CENTER- 327 HIGH STREET- REPAVE LOT

Before





After







` Wesleyan University





After



√ Wesleyan University


FOSS 5.5 BLUESTONE STAIRS REPLACEMENT

Before



After











Wesleyan University

FOSS 7 BLUESTONE STAIRS REPLACEMENT

Before



After




√ Wesleyan University

FY 20 Before and After

BUTTERFIELD A-LOT L REPAVE ACCESS DRIVE

Before



After









C LOT - CHURCH ST - CURB / STAIR REPAIRS

After

Before















√ Wesleyan University

EXLEY GENERATOR

Before







After



DOWNEY HOUSE ROOM 100 -CLASSROOM UPGRADE











Before




After



、ヿ ` Wesleyan University



After




Wesleyan University






Before



After







HALL-ATWATER 056 - CLASSROOM UPGRADE

Before





Wesleyan University





FY 20 Before and After

Before

√ Wesleyan University

ZILKHA ROOM 202 - CLASSROOM UPGRADE / LOBBY





