



Wesleyan University

Capital & Major Maintenance Projects

Before & After Photos

FY 2019/2020

Capital Projects

291 MAIN STREET - RENOVATION FURNITURE-
BEFORE



291 MAIN STREET - RENOVATION
FURNITURE





Before




In Progress

FY 20 Before and After

In Progress

CENTER FOR FILM STUDIES – CONSTRUCTION NEW ADDITION AND RENOVATION



Before



After



Before





Before



After



COMP 12: LED LIGHTING
UPGRADES

Foss Hill Drive LED lighting Upgrade
Central Power Plant LED Lighting
Van Vleck Observatory LED Lighting Upgrade
291 Main Street LED Lighting Upgrade
Memorial Chapel/ Zelnick Pavillion
Allbritton LED Lighting Upgrade

EXLEY DATA CENTER COMPREHENSIVE ENERGY
PHASE 12: EXLEY DATA CENTER HVAC UPGRADES

Before

After




**FIRE SAFETY UPGRADES – NEW FIRE ALARM & FIRE
SPRINKLER SYSTEMS** 31 NEW UNDERGRAD BEDS CREATED



38/40 Brainerd Avenue




47 Brainerd Avenue



39 Brainerd Avenue

CFA A ADZENYAH REHEARSAL HALL - ADA UPGRADES – HOW WE GOT THERE











FREEMAN ATHLETIC CENTER INFORMAL LEARNING SPACE- BEFORE



FREEMAN ATHLETIC CENTER INFORMAL LEARNING SPACE- AFTER



Before



After



Before



After



Before



After





After



Before



Before



After





Before



After




**SANIGLAZE TILE
RESTORATION**

Public Affair Center



Foss 1-4 Bathrooms



SANIGLAZE TILE RESTORATION

Russell House



Fisk Hall



Major Maintenance FY20 Projects

274 COURT STREET - APARTMENT #103 - KITCHEN
RENOVATION

Before



After



Before



After





Before



After



Before



After



Before



After



Before



After



Before




After



Before



After



Before



After



Construction



Before



After



Before



After



OLIN MEMORIAL LIBRARY – COMMON AREA CARPET REPLACEMENT 1ST & 2ND FLOORS



Before



After



Before



After



Before:
Men



Before:
Women



After

202 WASHINGTON ST - FLOORING REPLACEMENT /REFINISHING

Before



After



Before



After



110 CHURCH ST - EXTERIOR WATERPROOFING

Before




After



Before



After



Before



After



Before



After



Before



After



Before



After



CFA CROWELL CONCERT HALL -MECHANICAL SYSTEM UPGRADES AND SKYLIGHT REPLACEMENT

Before



After



Before

Men's Room



After



Before

Women's Room



After



Before



After





FY 20 Before and After

CFA P THEATER – INSTALL GALLERY SAFETY
RAILS



After

Before



FY 20 Before and After

WOODFRAME STRUCTURAL FLOOR REPAIRS

Before



After



Before



33 BRAINARD AVE- ROOF REPLACEMENT

Before



After



Before




After



Before



After



Before



After



Before



After



Before



After



Before



After



Before



After



Before



After



ALSOP HOUSE- WOOD SOFFIT REPAIRS

FY 20 Before and After

Before



After



Before



After



Before



After



DAVISON HEALTH CENTER CLINIC ROOF REPLACEMENT

Before




After





Before

After



FREEMAN ATHLETIC CENTER - FIRE ALARM UPGRADE

FY 20 Before and After



Before





Before



After



Before



After



Before



After



FY 20 Before and After

FOSS HILL 6-7 CONNECTOR – ROOF REPLACEMENT

Before



After



Before



After



Before



After



CFA ART STUDIO SOUTH – ROOF REPLACEMENT

FY 20 Before and After

Before



After




FY 20 Before and After

HALL ATWATER -265 CHURCH ST-SIDEWALK
REPAIR

Before



After



Before



After




MALCOLM X- 345 HIGH ST- BLUESTONE STAIR REPAIRS

FY 20 Before and After

Before



After



FOSS 5.5 BLUESTONE STAIRS REPLACEMENT

Before



After



FOSS 7 BLUESTONE STAIRS REPLACEMENT

Before



After



FY 20 Before and After

BUTTERFIELD A-LOT L REPAVE ACCESS
DRIVE

Before



After



Before

After



FY 20 Before and After

C LOT - CHURCH ST - CURB / STAIR REPAIRS

After

Before



Before

After





Before

After



Before



After



Before



After



Before



After



Before



After



Before



After



FY 20 Before and After

HALL-ATWATER 056 - CLASSROOM
UPGRADE

Before



After



ZILKHA ROOM 202 - CLASSROOM UPGRADE / LOBBY

FY 20 Before and After

Before



After

